

oistway must be in accordance with "Safety Code for Elevators and A17.1) and all state and local codes.	Customer:
Y: Due to close running clearances owner/agent must ensure that and square and is in accordance with dimensions on these drawings.	Project:
L: The rail wall must be reinforced with double 2x12 planks as shown e machine and rail system requires these 2x12 planks for support.	
Machine room may be located within the hoistway on the bottom floor ent to the hoistway (behind the rail wall). The machine room must have oor. This door must remained locked at all times.	Location:
A lockable fused disconnect must be provided in accordance with local	
ne supply must be a 115V, 20A dedicated circuit.	Date:
ist meet local fire code. Interlock devices are provided and must be s directed in the installation guide. Hoistway doors included.	

Sheetrock inside and outside hoistway

Center Line

2x12 Planks between 2x4 studs

2x4 construction